

Contents

Firmware Overview

Introduction

Firmware information 2

Requirements and limitations 2

Update Instructions

Precautions 2

Performing the update 2

Introduction

Firmware Information

This Firmware Upgrade is specifically intended for users with the Alpine iLX-W650E. There is one firmware update per unit. If you are unsure if you need this update please contact your nearest Alpine dealer.

Note: The update is not required for Alpine units with Firmware versions 1.004_0818 (December 2020) or higher.

Requirements and limitations

- Windows XP / Windows 7 / Windows 8 / Windows 10
- Formatted USB flash drive with a minimum capacity of 1 GB

Update Instructions


Precautions

- Do NOT switch off the vehicle / switch off the unit's power nor remove the USB flash drive during the update process.
- Do NOT use compressed zip-files for update and do NOT change file names.
- Do NOT store any other folders and files on the USB stick
- Do NOT operate the Alpine unit whilst updating nor update the Alpine unit while driving
- The unit is updated via USB connection. Plug in the USB flash drive into the USB socket of the Alpine unit to initialise the update


Performing the update

- 1 Un-zip the downloaded folder into the root directory of the USB flash drive.
- 2 Turn the vehicle on and plug in the USB flash drive into the USB socket of the Alpine unit.
- 3 Go to the 'INFORMATION' page via the below menu steps and select 'Firmware Upgrade' from the display.

SETUP → INFORMATION




- 4 The firmware upgrade will take several minutes to complete. Once the firmware upgrade is complete, the Alpine unit will reset.



- 5 Following the firmware upgrade, perform a system reset. Go to the 'SYSTEM' page via the below menu steps and select 'Reset'.

SETUP → SYSTEM



- 6 Go to the 'INFORMATION' page via the below menu steps to confirm the firmware upgrade is successful. See 'System Version: V1.004_0818'.

SETUP → INFORMATION

